

## First (Midlands West)

First Midland Red Buses Limited, Abbey Lane, Leicester, Leicestershire, LE4 0DA (PD0000480)

Leicester Citybus Limited, Abbey Lane, Leicester, Leicestershire, LE4 0DA (PF0007035)

Northampton Transport Limited, Abbey Lane, Leicester, Leicestershire, LE4 0DA (PF0007045)

### Depots:

HD	Friar Street, Hereford, Herefordshire, HR4 0AS
KR	Island Drive, Kidderminster, Worcestershire, DY10 1EZ
LR	Abbey Lane, Leicester, Leicestershire, LE4 0DA
NN	The Bus Depot, St James Road, Northampton, Northamptonshire, NN5 5JD
RH	Plymouth Road, Redditch, Worcestershire, B97 4PX
WR	Padmore Street, Worcester, Worcestershire, WR1 2PA

Part of First Group PLC.

<b>31451</b>	N962SOS NN	Volvo Olympian YN2RV18V3	Alexander RL	H47/32F	1995
<b>31452</b>	N963SOS RH	Volvo Olympian YN2RV18V3	Alexander RL	H47/32F	1995
<b>31453</b>	N964SOS NN	Volvo Olympian YN2RV18V3	Alexander RL	H47/32F	1995
<b>31454</b>	N965SOS NN	Volvo Olympian YN2RV18V3	Alexander RL	H47/32F	1995
<b>31553</b>	E127DRS WR	Volvo Olympian ONCL10/2RZ	Alexander RH	H49/29F	1987

31553 ex First Aberdeen, 2008

<b>32053 - 32065</b>	Volvo B7TL-57	Alexander ALX400	H47/29F	2000	
<b>32053</b>	W213XBD LR	<b>32056</b> W216XBD LR	<b>32059</b> W219XBD LR	<b>32062</b> W422XBD LR	<b>32064</b> W224XBD LR
<b>32054</b>	W214XBD LR	<b>32057</b> W217XBD LR	<b>32061</b> W221XBD LR	<b>32063</b> W223XBD LR	<b>32065</b> W425SRP LR
<b>32055</b>	W215XBD LR	<b>32058</b> W218XBD LR			

<b>32066 - 32277</b>	Volvo B7TL-57	Alexander ALX400	H47/27F	2001, 2002	
<b>32066</b>	KP51VZO LR	<b>32073</b> KP51VZZ LR	<b>32080</b> KP51WBK LR	<b>32087</b> KP51WBZ LR	<b>32094</b> KP51WCR LR
<b>32067</b>	KP51VZR LR	<b>32074</b> KP51WAJ LR	<b>32081</b> KP51WBL LR	<b>32088</b> KP51WCA LR	<b>32095</b> KP51WCW LR
<b>32068</b>	KP51VZS LR	<b>32075</b> KP51WAO LR	<b>32082</b> KP51WBO LR	<b>32089</b> KP51WCF LR	<b>32096</b> KP51WCX LR
<b>32069</b>	KP51VZT LR	<b>32076</b> KP51WAU LR	<b>32083</b> KP51WBT LR	<b>32090</b> KP51WCG LR	<b>32097</b> KP51WCY LR
<b>32070</b>	KP51VZW LR	<b>32077</b> KP51WBD LR	<b>32084</b> KP51WBU LR	<b>32091</b> KP51WCJ LR	<b>32098</b> KP51WDD LR
<b>32071</b>	KP51VZX LR	<b>32078</b> KP51WBG LR	<b>32085</b> KP51WBV LR	<b>32092</b> KP51WCN LR	<b>32099</b> KP51WDE LR
<b>32072</b>	KP51VZY LR	<b>32079</b> KP51WBJ LR	<b>32086</b> KP51WBY LR	<b>32093</b> KP51WCO LR	<b>32277</b> KP51WDF LR

<b>32627 - 32650</b>	Volvo B7TL-57	Wright Eclipse Gemini	H47/29F		
<b>32627</b>	KP54KAO LR	<b>32632</b> KP54KBJ LR	<b>32639</b> KP54AZA LR	<b>32643</b> KP54AZF LR	<b>32647</b> KP54AZN LR
<b>32628</b>	KP54KAU LR	<b>32633</b> KP54LAE LR	<b>32640</b> KP54AZB LR	<b>32644</b> KP54AZG LR	<b>32648</b> KP54KBK LR
<b>32629</b>	KP54KAX NN	<b>32634</b> KP54LAO LR	<b>32641</b> KP54AZC LR	<b>32645</b> KP54AZJ LR	<b>32649</b> KP54KBN LR
<b>32630</b>	KP54KBE NN	<b>32635</b> KP54MGW LR	<b>32642</b> KP54AZD LR	<b>32646</b> KP54AZL LR	<b>32650</b> KP54KBO LR
<b>32631</b>	KP54KBF LR				

<b>33401 - 33405</b>	ADL Trident	ADL ALX400	H47/27F	2004	
<b>33401</b>	VX54MTV WR	<b>33402</b> VX54MTY WR	<b>33403</b> VX54MTZ RH	<b>33404</b> VX54MUA WR	<b>33405</b> VX54MUB WR

<b>34287</b>	P187TGD NN	Volvo Olympian YN2RV18V326	Alexander RL	H47/32F	1996
<b>34289</b>	P189TGD WR	Volvo Olympian YN2RV18V326	Alexander RL	H47/32F	1996
<b>37146</b>	YN06UPZ LR	Volvo B7TL-57	Wright Eclipse Gemini	H45/29F	2006

34287, 34289 ex First Devon and Cornwall, 2005; 37146 ex First South Yorkshire, 2008

<b>38082 - 38121</b>	Volvo Citybus B10M-50	Alexander RV	DPH47/35F	1987 - 1992	
<b>38082</b>	LSU717 NN	<b>38097</b> J297GNV WR	<b>38098</b> J298GNV NN	<b>38099</b> J299GNV NN	<b>38121</b> K121URP NN

<b>38122</b>	WSU481 NN	Volvo Citybus B10M-50	East Lancashire	H45/39F	1992
<b>38125</b>	K125URP RH	Volvo B10M	Alexander RL	DPH47/35F	1992
<b>38126</b>	K126URP RH	Volvo B10M	Alexander RL	DPH47/35F	1992
<b>40245</b>	M101RRJ KR	Dennis Dart 9.8SDL3054	Northern Counties	B39F	1995
<b>40269</b>	N637CDB KR	Dennis Dart 9.8SDL3054	Northern Counties	B39F	1995
<b>40284</b>	N653CDB KR	Dennis Dart 9.8SDL3054	Plaxton Pointer	B40F	1995

40245 - 40284 ex First Manchester, 2007

<b>40805 - 42220</b>	Dennis Dart 10.6SDA SLF	Plaxton Pointer 2	B37F	1997	
<b>40805</b>	R312GHS WR	<b>40837</b> R674DUS WR	<b>42180</b> R610YCR KR	<b>42219</b> R219MSA WR	<b>42220</b> R220MSA WR
<b>40833</b>	R670DUS WR	<b>40838</b> R675DUS WR	<b>42217</b> R217MSA WR		

40805 - 40838 ex First Glasgow, 2006; 42180 ex First Hampshire and Dorset, 2009; 42217 - 42220 ex First Cymru, 2002

<b>42351 - 42356</b>	Dennis Dart 10.2SDA SLF	Caetano Nimbus	B34F	2001	
<b>42351</b>	Y351AUY WR	<b>42352</b> Y352AUY WR	<b>42353</b> Y353AUY WR	<b>42354</b> Y354AUY WR	<b>42356</b> Y356AUY WR

42351, 42354, 42356 are branded for UniShuttle Service 31

<b>42401 - 42406</b>	Dennis Dart 10.2SDA SLF	Plaxton Pointer	B34F	1996	
<b>42401</b>	P401MLA WR	<b>42403</b> P403MLA WR	<b>42404</b> P404MLA WR	<b>42405</b> P405MLA KR	<b>42406</b> P406MLA WR
<b>42402</b>	P402MLA KR				

42401 - 42406 ex First London, 2008

<b>42455</b>	R445CCV WR	Dennis Dart 10.7SDA SLF	Plaxton Pointer 2	B35F	1997
<b>42641</b>	N341EUY WR	Dennis Dart 10.2SDA SLF	Plaxton Pointer 2	B33F	1996

42455 ex First Devon and Cornwall, 2008

<b>42889 - 42894</b>	ADL Dart 10.6SDA SLF	Plaxton Pointer 2	B40F	2004	
<b>42889</b>	VX54MUC KR	<b>42891</b> VX54MUP KR	<b>42892</b> VX54MUU WR	<b>42893</b> VX54MUV HD	<b>42894</b> VX05JWW HD
<b>42890</b>	VX54MUO KR				

<b>46929</b>	N829FLW KR	Dennis Dart 9SDL3053	Plaxton Pointer	B32F	1995
<b>46930</b>	N830FLW KR	Dennis Dart 9SDL3053	Plaxton Pointer	B32F	1995
<b>46931</b>	N831FLW KR	Dennis Dart 9SDL3053	Plaxton Pointer	B32F	1995
<b>46932</b>	N832FLW KR	Dennis Dart 9SDL3053	Plaxton Pointer	B32F	1995

46929 - 46932 ex First Berkshire, 2004

<b>47001 - 47013</b>	Dennis Dart 9.8SDL3054	Plaxton Pointer	DP35F	1995	
<b>47001</b>	N301XAB HD	<b>47003</b> N303XAB HD	<b>47005</b> N305XAB HD	<b>47007</b> N307XAB HD	<b>47013</b> N313XAB KR
<b>47002</b>	N302XAB HD	<b>47004</b> N304XAB HD	<b>47006</b> N306XAB HD	<b>47008</b> N308XAB HD	

<b>50296</b>	W327DWX HD	Optare Solo M850	Optare	B27F	2000
<b>53040</b>	VU02PKX HD	Optare Solo M850	Optare	B22F	2002
<b>53041</b>	VU02PKY HD	Optare Solo M850	Optare	B22F	2002

50296 ex First Bradford, 2005

<b>53042 - 53073</b>	Optare Solo M850	Optare	B26F	2003	
<b>53042</b>	VU03YJT KR	<b>53046</b> VU03YJY WR	<b>53050</b> VU03YKD NN	<b>53060</b> VX53OEO HD	<b>53064</b> VX53OEU HD
<b>53043</b>	VU03YJV WR	<b>53047</b> VU03YJZ WR	<b>53051</b> VU03YKE NN	<b>53061</b> VX53OEP HD	<b>53071</b> KX06APV NN
<b>53044</b>	VU03YJW WR	<b>53048</b> VU03YKB WR	<b>53058</b> VX03OEV NN	<b>53062</b> VX53OER HD	<b>53072</b> KX06APY NN
<b>53045</b>	VU03YJX WR	<b>53049</b> VU03YKC NN	<b>53059</b> VX03OEN NN	<b>53063</b> VX53OET HD	<b>53073</b> KX06APZ NN

<b>61013</b>	N475JUG KR	Dennis Lance	SFD211BR2SGL	Plaxton Verde	B49F	1996
<b>61016</b>	N478JUG KR	Dennis Lance	SFD211BR2SGL	Plaxton Verde	B49F	1996
<b>61148</b>	MV02VBU NN	Volvo B7L-60		Wright Eclipse Urban	B41F	2002

61013, 61016 ex First Bradford, 2004

**66301 - 66348** Volvo B7L-60 Wright Eclipse Urban B41F 2002

<b>66301</b>	KV02VVC NN	<b>66311</b>	KV02VVN LR	<b>66321</b>	KV02VVZ LR	<b>66331</b>	MV02VBU NN	<b>66340</b>	MV02VCP NN
<b>66302</b>	KV02VVD LR	<b>66312</b>	KV02VVO LR	<b>66322</b>	KV02VMA LR	<b>66332</b>	MV02VBX NN	<b>66341</b>	MV02VCT NN
<b>66303</b>	KV02VVE LR	<b>66313</b>	KV02VVP LR	<b>66323</b>	KV02VMB LR	<b>66333</b>	MV02VBY NN	<b>66342</b>	MV02VCU NN
<b>66304</b>	KV02VVF LR	<b>66314</b>	KV02VVR LR	<b>66324</b>	MV02VAX NN	<b>66334</b>	MV02VBZ NN	<b>66343</b>	MV02VCW NN
<b>66305</b>	KV02VVG LR	<b>66315</b>	KV02VVS LR	<b>66325</b>	MV02VAY NN	<b>66335</b>	MV02VCA NN	<b>66344</b>	MV02VCX NN
<b>66306</b>	KV02VVH LR	<b>66316</b>	KV02VVT LR	<b>66326</b>	MV02VBA NN	<b>66336</b>	MV02VCC NN	<b>66345</b>	MV02VCY NN
<b>66307</b>	KV02VVJ LR	<b>66317</b>	KV02VVU LR	<b>66327</b>	MV02VBB NN	<b>66337</b>	MV02VCM NN	<b>66346</b>	MV02VCZ NN
<b>66308</b>	KV02VVK NN	<b>66318</b>	KV02VWV LR	<b>66328</b>	MV02VBC NN	<b>66338</b>	MV02VCN NN	<b>66347</b>	MV02VDA NN
<b>66309</b>	KV02VVL LR	<b>66319</b>	KV02VVX LR	<b>66329</b>	MV02VBD NN	<b>66339</b>	MV02VCO NN	<b>66348</b>	MV02VDC NN
<b>66310</b>	KV02VVM LR	<b>66320</b>	KV02VVY LR	<b>66330</b>	MV02VBE NN				

**66962 - 66987** Volvo B7L-60 Wright Eclipse Urban B43F 2005

<b>66962</b>	KX05MHY LR	<b>66968</b>	KX05MJO LR	<b>66973</b>	KX05AOD LR	<b>66978</b>	KX05MHE WR	<b>66983</b>	KX05MHM WR
<b>66963</b>	KX05MHZ LR	<b>66969</b>	KX05MJU LR	<b>66974</b>	KX05AOE LR	<b>66979</b>	KX05MHF WR	<b>66984</b>	KX05MHN WR
<b>66964</b>	KX05MJE LR	<b>66970</b>	KX05MJV LR	<b>66975</b>	KX05MGY LR	<b>66980</b>	KX05MHJ WR	<b>66985</b>	KX05MHO WR
<b>66965</b>	KX05MJF LR	<b>66971</b>	KX05MJY LR	<b>66976</b>	KX05MGZ WR	<b>66981</b>	KX05MHK WR	<b>66986</b>	KX05MHU WR
<b>66966</b>	KX05MJJ LR	<b>66972</b>	KX05AOC LR	<b>66977</b>	KX05MHA WR	<b>66982</b>	KX05MHL WR	<b>66987</b>	KX05MHX WR
<b>66967</b>	KX05MJK LR								

**67202 - 67237** Dennis Lance 11SDA3107 Plaxton Verde B49F 1994, 1995

<b>67202</b>	L202AAB KR	<b>67209</b>	L209AAB RH	<b>67214</b>	L214AAB KR	<b>67219</b>	L219AAB RH	<b>67235</b>	L235AAB WR
<b>67205</b>	L205AAB KR	<b>67211</b>	L211AAB RH	<b>67215</b>	L215AAB WR	<b>67232</b>	L232AAB WR	<b>67236</b>	L236AAB RH
<b>67206</b>	L206AAB KR	<b>67212</b>	L212AAB KR	<b>67218</b>	L218AAB NN	<b>67234</b>	L234AAB WR	<b>67237</b>	L237AAB RH
<b>67208</b>	L208AAB RH	<b>67213</b>	L213AAB KR						

67218, 67219 ex First Cymru, 2002

**67238 - 67250** Dennis Lance 11SDA3113 Plaxton Verde B49F 1995

<b>67238</b>	M238MRW KR	<b>67241</b>	M241MRW RH	<b>67244</b>	M244MRW KR	<b>67247</b>	M247MRW KR	<b>67249</b>	M249MRW WR
<b>67239</b>	M239MRW KR	<b>67242</b>	M242MRW WR	<b>67245</b>	M245MRW RH	<b>67248</b>	M248MRW RH	<b>67250</b>	M250MRW RH
<b>67240</b>	M240MRW WR	<b>67243</b>	M243MRW RH	<b>67246</b>	M246MRW RH				

67241 is in Green Bus Livery

<b>67251</b>	M251MRW RH	Dennis Lance	11SDA3113	Plaxton Verde	B51F	1995
<b>67253</b>	M253MRW WR	Dennis Lance	11SDA3113	Plaxton Verde	B51F	1995
<b>67254</b>	M254MRW WR	Dennis Lance	11SDA3113	Plaxton Verde	B51F	1995
<b>67255</b>	M255MRW WR	Dennis Lance	11SDA3113	Plaxton Verde	B51F	1995
<b>67256</b>	M256MRW RH	Dennis Lance	11SDA3113	Plaxton Verde	B49F	1995
<b>67301</b>	M221EAF WR	Dennis Lance	SLF	Wright Pathfinder 320	B40F	1994
<b>67311</b>	ODZ8911 RH	Dennis Lance	11SDA3002 SLF	Wright Pathfinder	B39F	1994
<b>67312</b>	ODZ8912 RH	Dennis Lance	11SDA3002 SLF	Wright Pathfinder	B39F	1994
<b>67313</b>	ODZ8913 RH	Dennis Lance	11SDA3002 SLF	Wright Pathfinder	B38F	1994
<b>67314</b>	ODZ8914 WR	Dennis Lance	11SDA3002 SLF	Wright Pathfinder	B38F	1994
<b>67315</b>	ODZ8915 WR	Dennis Lance	11SDA3002 SLF	Wright Pathfinder	B39F	1994
<b>67318</b>	ODZ8918 WR	Dennis Lance	11SDA3002 SLF	Wright Pathfinder	B34F	1994
<b>67319</b>	ODZ8919 WR	Dennis Lance	11SDA3002 SLF	Wright Pathfinder	B39F	1994
<b>67321</b>	ODZ8921 WR	Dennis Lance	11SDA3002 SLF	Wright Pathfinder	B39F	1994
<b>67322</b>	ODZ8922 WR	Dennis Lance	11SDA3002 SLF	Wright Pathfinder	B34F	1994
<b>67323</b>	ODZ8923 WR	Dennis Lance	11SDA3002 SLF	Wright Pathfinder	B39F	1994
<b>67324</b>	ODZ8924 WR	Dennis Lance	11SDA3002 SLF	Wright Pathfinder	B39F	1994
<b>67600</b>	SN53KKY RH	Transbus Enviro	300	Transbus Enviro 300	B49F	2004

67301 ex First London, 2002; 67311, 67312 ex First Somerset and Avon, 2004; 67313 - 67324 ex First Bristol, 2003; 67600 ex First Manchester, 2004

<b>67601</b>	VX53VJV RH	Transbus Enviro 300	Transbus Enviro 300	B44F	2004
<b>67602</b>	VX53VJZ RH	Transbus Enviro 300	Transbus Enviro 300	B44F	2004
<b>67603</b>	VX53VKA HD	Transbus Enviro 300	Transbus Enviro 300	B44F	2004
<b>67604</b>	VX53VKB RH	Transbus Enviro 300	Transbus Enviro 300	B44F	2004

<b>67631 - 67664</b>	ADL Enviro 300	ADL Enviro 300	B44F	2004, 2005	
<b>67631</b>	VX54MOV RH	<b>67638</b> VX54MPZ RH	<b>67645</b> VX54MSY RH	<b>67652</b> VX05LVS WR	<b>67659</b> VX05LWC WR
<b>67632</b>	VX54MPE RH	<b>67639</b> VX54MRO RH	<b>67646</b> VX54MTE WR	<b>67653</b> VX05LVT WR	<b>67660</b> VX05LWD WR
<b>67633</b>	VX54MPF RH	<b>67640</b> VX54MRU RH	<b>67647</b> VX54MTF WR	<b>67654</b> VX05LVU WR	<b>67661</b> VX05LWE WR
<b>67634</b>	VX54MPO RH	<b>67641</b> VX54MRV RH	<b>67648</b> VX54MTJ WR	<b>67655</b> VX05LVV WR	<b>67662</b> VX05LWF WR
<b>67635</b>	VX54MPU RH	<b>67642</b> VX54MRY RH	<b>67649</b> VX54MTK WR	<b>67656</b> VX05LVW WR	<b>67663</b> VX05LWG WR
<b>67636</b>	VX54MPV RH	<b>67643</b> VX54MSO RH	<b>67650</b> VX54MTO RH	<b>67657</b> VX05LVY WR	<b>67664</b> VX05LWH WR
<b>67637</b>	VX54MPY RH	<b>67644</b> VX54MSU RH	<b>67651</b> VX54MTU RH	<b>67658</b> VX05LVZ WR	

<b>68507 - 68520</b>	BMC 1100FE	BMC	B60F	2004	
<b>68507</b>	KP54AHP NN	<b>68508</b> KP54AHU NN	<b>68509</b> KP54AHY NN	<b>68510</b> KP54ANR NN	<b>68520</b> KP54AZU WR

68507 - 68520 are in an overall yellow livery for School Services

68520 ex First West Yorkshire, 2007

#### Ancillary Vehicles:

<b>35351</b>	A751THV NN	MCW Metrobus DR101/19	MCW	H43/28D	1984	DT
<b>39167</b>	G667FKA LR	Dennis Dominiator DDA1031	East Lancashire	H47/29F	1990	DT
<b>52501</b>	R501CNP LR	Mercedes-Benz Vario 0.814D	Plaxton Beaver 2	B22F	1998	CV
<b>52502</b>	R502CNP KR	Mercedes-Benz Vario 0.814D	Plaxton Beaver 2	B22F	1998	
<b>52504</b>	R504CNP LR	Mercedes-Benz Vario 0.814D	Plaxton Beaver 2	B22F	1998	CV
<b>54097</b>	LT02NVC LR	Mercedes-Benz 411CDI	Koch	M13	2002	CV
<b>54099</b>	LT02NVB LR	Mercedes-Benz 411CDI	Koch	M13	2002	CV
<b>60311</b>	M516PNA WR	Volvo B10B-58	Wright Endurance	DP50F	1995	DT
<b>60329</b>	N534WVR WR	Volvo B10B-58	Wright Endurance	DP50F	1995	DT
<b>60340</b>	N545WVR KR	Volvo B10B-58	Wright Endurance	DP50F	1995	DT
<b>62702</b>	G102HNP WR	Leyland Lynx LX2R11C15Z4R	Leyland Lynx	B49F	1990	DT
<b>67623</b>	L623XFP ??	Dennis Falcon SDA422	Northern Counties	B48F	1993	DT
<b>90256</b>	C930GYD ??	Ford Transit 190D	Robin Hood	B16F	1986	DT
<b>90274</b>	NOE614R WR	Leyland Leopard PSU3D/4R	Plaxton Supreme 3	B--F	1976	RV

CV = Crew Vehicle; DT = Driver Trainer; RV = Recovery Vehicle

60329, 60340 ex First Manchester, 2008; 90256 ex First Southern National, ????

#### Withdrawn Vehicles:

<b>31378</b>	L166UNS KR	Leyland Olympian ON2R50C13	Alexander RL	H47/31F	1993	
<b>31379</b>	L167UNS KR	Leyland Olympian ON2R50C13	Alexander RL	H47/31F	1993	
<b>31380</b>	L169UNS RH	Leyland Olympian ON2R50C13	Alexander RL	H47/31F	1993	
<b>38083</b>	F83XBD NN	Volvo Citybus B10M-50	Alexander RV	DPH47/35F	1987	
<b>40261</b>	N629CDB KR	Dennis Dart 9.8SDL3054	Northern Counties	B39F	1995	
<b>46103</b>	K903CVW KR	Dennis Dart 9SDL3016	Plaxton Pointer	B35F	1992	
<b>47011</b>	N311XAB KR	Dennis Dart 9.8SDL3054	Plaxton Pointer	DP35F	1995	
<b>52503</b>	R503CNP KR	Mercedes-Benz Vario 0.814D	Plaxton Beaver 2	B22F	1998	
<b>52511</b>	S511SWP KR	Mercedes-Benz Vario 0.814D	Plaxton Beaver 2	B22F	1998	
<b>60374</b>	J461OVU LR	Volvo B10M-60	Northern Counties	B49F	1991	DT
<b>60459</b>	G604NWA NN	Volvo B10M-55	Alexander PS	B51F	1990	DT
<b>60460</b>	G605NWA LR	Volvo B10M-55	Alexander PS	B51F	1990	DT

31378 - 31380 ex First Glasgow, 2004; 40261 ex First Manchester, 2007; 46103 ex First Leicester, 2003; 60459 ex First Yorkshire, ????

<b>67111 - 67120</b>	Dennis Lance 11SDA3112	Plaxton Verde	DP45F	1993	
<b>67111</b>	L821HCY KR	<b>67113</b> L823HCY NN	<b>67114</b> L824HCY NN	<b>67117</b> L827HCY NN	<b>67120</b> L820HCY KR
<b>67112</b>	L822HCY NN				

67112 - 67120 ex First Cymru, 2004

---

<b>67201 - 67233</b>	Dennis Lance 11SDA3107	Plaxton Verde	B49F	1994
<b>67201</b> L201AAB KR	<b>67204</b> L204AAB NN	<b>67210</b> L210AAB NN	<b>67231</b> L231AAB WR	<b>67233</b> L233AAB NN
<b>67203</b> L203AAB NN	<b>67207</b> L207AAB RH	<b>67217</b> L217AAB RH		

---

<b>67252</b> M252MRW NN	Dennis Lance 11SDA3113	Plaxton Verde	B51F	1995
-------------------------	------------------------	---------------	------	------

---